

WIPE OUT

OVEN and GRILL RENOVATOR

TECHNICAL DATA

GENERAL DESCRIPTION

WIPE OUT's penetrating solvent action eliminates the need for harsh abrasive action. WIPE OUT quickly dissolves heavy baked on grease, fat, soot, carbon and food buildups.

AREAS OF APPLICATION

Handy aerosol WIPE OUT is an ideal industrial strength oven renovator for any establishment that maintains stoves, ovens, griddles, deep fryers, non-aluminum barbeques and grills such as commercial kitchens, housing authorities, restaurants, hotels, schools, apartment complexes, hospitals, etc.

SPECIAL FEATURES

Ends Oven Cleaning Drudgery - simply spray on, let thick foam penetrate and "wipe out" grease and food buildup with just a swipe. No harsh scrubbing.

Handy Aerosol - no special equipment needed. No pre-mixing necessary. WIPE OUT is always ready.

Economically Effective - usually only one application is necessary. Removes encrustations even daily maintenance products can't remove.

Non-Flammable - no flammable fumes to cause flash fires.

Works Well On Cold or Warm Ovens - unlike common oven cleaners, WIPE OUT works well on both cold and warm ovens.

No Toxic Residues - WIPE OUT is completely soluble. Wipes out clearly leaving no residues, odour or problems.

USE DIRECTIONS

Wear long-sleeved impervious gloves and chemical splash goggles. Remove racks from oven.

- 1/ Shake vigorously. Hold can upright.
- 2/ Spray WIPE OUT with slow sweeping motion coating the entire encrusted areas from 20 to 30cm/10 to 12 inches away.
- 3/ For pre-warmed ovens (turn off electric current or gas pilot lights after warming) allow to stand for 5 to 10 minutes. For cold ovens allow to set for 10 to 30 minutes.
- 4/ With a paper towel, damp sponge or cloth, thoroughly wipe surface clean. Follow with thorough potable water rinse to remove any residue. Repeat process for hard to clean or heavily caked areas.

CAUTION: DO NOT USE ON SELF-CLEANING OVENS. DO NOT USE ON ALUMINUM, PAINTED SURFACES, ASPHALT TILE OR LINOLEUM. Do not spray on electrical connections. Avoid contact with thermostats, bulbs, chrome or enameled surfaces. Turn off current in electric ovens and pilot lights in gas ovens to prevent shorting or accidentally extinguishing the pilot light.

PHYSICAL PROPERTIES - AEROSOL

WIPE OUT consists of a blend of potassium hydroxide, solvents and surfactants.

Type	Alkaline Aerosol Oven Renovator
Appearance	White Foam
Odour	Lemon
Viscosity	Sprays Liquid/Foams On Contact
Flammability	Non-Flammable
SG	1.085
pH	13 - 14
Solubility in Water	Complete
Toxicity (concentrate)	Severe Eye/Skin Burns Harmful if Swallowed Avoid ingestion or Inhalation

APPROVALS/CERTIFICATIONS



Canadian Food Inspection Agency

**FOR USE IN
INDUSTRIAL, INSTITUTIONAL, COMMERCIAL
AND FOOD PROCESSING ENVIRONMENTS**

PACKAGING

Aerosol Case (12 x 510g cans)



DM2402



25 PLANCHET ROAD, CONCORD, ONTARIO, CANADA L4K 2C5
PHONE: 905.532.9000 FAX: 905.532.9003 WEBSITE: www.mega-lab.com

